

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED
FEB 02 1999
DIVISION OF
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/93 To (mo./yr.) 12/93
2. DOGM File Number (Mine No): M /045 /037
3. Mine Name: Morton Salt - Grantsville
4. Mineral(s) Mined (or permitted to mine): Solar Salt (NaCl)
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
1/4, 1/4, Section Township Range
1/4, 1/4, Section Township Range
1/4, 1/4, Section Township Range
7. Name of Operator or Company: Morton International, Inc., Morton Salt Division
8. Permanent Street Address: I-80 West Exit #84 P. O. Box 506
City, State, Zip: Grantsville, Utah 84029
Phone: 801/250-6335 **FAX 250-6306**
9. Company Representative (or designated operator):
Name: Gary C. Price
Title: Facility Manager
Business Address: I-80 West Exit #84 P.O. Box 506
City, State, Zip: Grantsville, Utah 84029
Phone: 801/250-6335
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 367,000 tons Solar Salt

3. How much additional acreage was disturbed during the past year? None

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

No new or additional surface disturbances occurred during the past year. Existing earth dykes are repaired periodically.

5. How much acreage was reclaimed during the past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

None

7. What is the total disturbed acreage at years end? 7810

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

The same disturbed acreage (7810) will be used for solar salt evaporation. There are no reclamation plans for the upcoming year.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted. N/A
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached. N/A (NOI pending approval by DOGM)

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Gary C. Price

Title of Operator:

Facility Manager

Signature of Operator:

Date:

1-31-94

ATTACHMENT "A"

Morton International Inc/ Morton Salt
Operator

Morton Salt - Grantsville
Mine Name

Tooele County, Utah

Permit Number

The legal description of lands

Township: 1N Range: 5W Section: 19

Township: 1N Range: 6W Sections: 24, 25, 26, 32, 33, 34, 35

Township: 1S Range: 5W Sections: 16, 19, 20, 21

Township: 1S Range: 7W Sections: 1, 2, 3, 10, 11, 12, 13, 14, 15

Township: 1S Range: 6W Sections: 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 13, 14, 15,
16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26,
27, 28, 29

TDA letter dated: